

# Switch 4200G Bootrom V2.04

## Release Notes

Hangzhou H3C Technologies Co., Ltd.



IToIP Solutions Expert

## Switch 4200G Bootrom V2.04 Release Notes

**Keywords:** Bootrom

**Abstract:** version information, updating, unresolved Problems and Avoidance Measures,  
List of Solved Problems.

**Abbreviations:**

Abbreviations	Full spelling
CPU	Central Processing Unit

# Table of Contents

<b>1 Version Information.....</b>	<b>5</b>
1.1 Version Number .....	5
1.2 Chronological List of Version .....	5
1.3 Version Compatibility Table .....	5
<b>2 Unresolved Problems and Avoidance Measures .....</b>	<b>5</b>
<b>3 Resolved Problems .....</b>	<b>6</b>
3.1 Resolved Problems in Version 2.04.....	6
3.2 Resolved Problems in Version 2.03.....	6
3.3 Resolved Problems in Version 2.02.....	6
3.4 Resolved Problems in Version 2.01.....	6
3.5 Resolved Problems in Version 2.00.....	6
3.6 Resolved Problems in Version 1.00.....	6

## List of Tables

**Table 1** Version Information Table ..... 5

**Table 2** Version Compatibility Table..... 5

# 1 Version Information

## 1.1 Version Number

**Version Information:** Version 2.04

## 1.2 Chronological List of Version

**Table 1** Version Information Table

Version Number	Based Version Number	Release Date	Remark
Version 2.04	Version 2.03	2010-09-10	None
Version 2.03	Version 2.02	2009-08-19	None
Version 2.02	Version 2.01	2009-06-30	None
Version 2.01	Version 2.00	2008-11-07	None
Version 2.00	Version 1.00	2007-11-20	None
Version 1.00	First release	2006-07-03	None

## 1.3 Version Compatibility Table

**Table 2** Version Compatibility Table

Hardware Platform	S5100-EI series
Equipment Model	4200G 12-Port 4200G 24-Port 4200G 48-Port 4200G PWR 24-Port
Flash Requirement	16M
Software Name	s3u02_04.btm
Host software	All released versions

# 2 Unresolved Problems and Avoidance Measures

None

## **3 Resolved Problems**

### **3.1 Resolved Problems in Version 2.04**

1. Change the ending year of copyright from 2009 to 2010

### **3.2 Resolved Problems in Version 2.03**

Support new flash.

### **3.3 Resolved Problems in Version 2.02**

1. Change the ending year of copyright from 2008 to 2009

2. LSOD08636

- First Found-in Version: V2.01
- Condition: There are too many files in the flash, and need more than one page to display.
- Description: The files displayed on the next page can not be deleted.

### **3.4 Resolved Problems in Version 2.01**

Support record the stack info of task.

### **3.5 Resolved Problems in Version 2.00**

1. LSOD06511

- First Found-in Version: V1.00
- Condition:  
Some switches have unsuited hardware parameters.
- Description:  
The switches reboot repeatedly during low temperature HASA test.

### **3.6 Resolved Problems in Version 1.00**

First release